

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

	<u>Top</u>	<u>Bottom</u>
Herrin Coal #6, Coal Section picks	436	440
Total Depth:		676

, from the Pennsylvanian

Electric Log filed.

Gamma Ray Perforation Log filed.

Driller's Log filed.

[Imaged Log viewing help: New users please read this.](#)

GET FILE	Cased Hole Log
GET FILE	Induction Electric Log
GET FILE	Scanned Documents
GET FILE	Scout Check Ticket
GET FILE	Handwritten Scout Ticket

Permit Date: 6/28/1955	Permit #: 2590	Reference #: 173
-------------------------------	-----------------------	-------------------------

COMPANY	Bassett, Clyde	
FARM	Wall	NO. 2
DATE DRILLED	April 3, 1956	COUNTY NO. 00318
AUTHORITY		
ELEVATION	566' GL -	
LOCATION	330'S line, 990'E line of NE SW	
COUNTY	Bond	API# 1200500318 00 15-5N-4W

Imaged Log viewing help: [New users please read this.](#)

[GET FILE](#)

Scanned Documents

Permit Date:	7/30/1981	Permit #:	15385	Reference #:	173
COMPANY	Farrar Oil Co., Inc.				
FARM	Wall, D.			NO. 2	
DATE DRILLED				COUNTY NO. 00318	
AUTHORITY					
ELEVATION	566' GL -				
LOCATION	330'S line, 990'E line of NE SW				
COUNTY	Bond	API#	1200500318 01	15-5N-4W	