

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

SAMPLE TOPS from Company

	<u>Top</u>	<u>Bottom</u>
Partlow Upper	512	566
Partlow Lower	629	
Total Depth:		640

Date Drilling Began: 2/23/2008

Casing 9 5/8" - 86' , cemented with 50 sacks
7" - 626' , cemented with 85 sacks

I.P. 1 bbls. of oil, 150 bbls. of water per day, from the Partlow Lower (626'-640')

Gamma Ray Neutron Casing Collar Log filed.

[Imaged Log viewing help: New users please read this.](#)

GET FILE	Cased Hole Log
GET FILE	Scanned Documents
GET FILE	Scout Check Ticket
GET FILE	Scout Check Ticket

Permit Date: 2/5/2008 **Permit #:** 59239 **Reference #:** 211378

COMPANY	Horizontal Systems, Inc.	NO. J-19-L
FARM	Partlow, M.	
DATE DRILLED	March 1, 2008	COUNTY NO. 27000
AUTHORITY	Company	
ELEVATION	581' KB - Company	
LOCATION	330'N line, 380'W line of NW NW NW	
COUNTY	Clark	API# 1202327000 00 35-9N-14W

[Imaged Log viewing help: New users please read this.](#)

[GET FILE](#)

Scanned Documents

Permit Date:	6/25/2008	Permit #:	59533	Reference #:	211378
COMPANY	Horizontal Systems, Inc.				
FARM	Partlow, M.			NO.	J-19-L
DATE DRILLED				COUNTY NO.	27000
AUTHORITY					
ELEVATION	581' KB - Company				
LOCATION	330'N line, 380'W line of NW NW NW				
COUNTY	Clark	API#	1202327000 01	35-9N-14W	

ILLINOIS STATE GEOLOGICAL SURVEY

Total Depth: 710

Casing 9 5/8" - 86' , cemented with 50 sacks
7" - 626' , cemented with 85 sacks
4 1/2" - 698' , cemented with 80 sacks

Perforated: 636' - 3639' , shots not reported

669' - 671' , shots not reported

Acidized: 636' - 671' , 400 gallons HCl acid

[Imaged Log viewing help: New users please read this.](#)

[GET FILE](#)

Scanned Documents

Permit Date:	Permit #: 59533	Reference #: 211378
COMPANY	Horizontal Systems, Inc.	
FARM	Partlow, M.	NO. J-19-L
DATE DRILLED	April 23, 2021	COUNTY NO. 27000
AUTHORITY		
ELEVATION	581' KB - Company	
LOCATION	330'N line, 380'W line of NW NW NW	
COUNTY	Clark	API# 1202327000 02 35-9N-14W