

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
red clay	0	15
clay and sandy soil	15	60
blue clay	60	120
blue sand mixed clay	120	210
blue clay	210	278
rock	278	317

Total Depth **317**

Casing: 6" 1945 BLACK from 0' to 297'

Size hole below casing: 6"

Water from rock at 0' to 317'

Static level 100' below casing top which is 8' above GL

Pumping level 130' when pumping at 12 gpm for 2 hr(s)

Permanent pump installed at ' on , with a capacity of gpm

Driller's Log filed.

Owner Address: R.R.#1 Belvidere, IL

Add'l loc info: Lot: 22 Subdivision: Valley View

Location source: Aerial Photograph verified

Verified by: VJA on 4/13/2021

Permit Date: October 24, 1972 **Permit #:** 20659

COMPANY Caper, Garland

FARM Monroe, Robert

DATE DRILLED March 14, 1973

NO. 170

ELEVATION 0'

COUNTY NO. 00668

LOCATION

LATITUDE 42.295614

LONGITUDE -88.900154

COUNTY Boone

API# 1200700668 00

17-44N-3E