

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
top soil	0	4
clay	4	62
sand & gravel	62	76
blue lime rock	76	93

Total Depth **93**

Casing: 5" STEEL from 0' to 80'

Size hole below casing: 5"

Water from rock at 80' to 93'

Static level 50' below casing top which is 1' above GL

Pumping level 70' when pumping at 30 gpm for 1 hr(s)

Permanent pump installed at 70' on 1/25/1981, with a capacity of 18 gpm

Driller's Log filed.

Owner Address: Lot #13, Easton View Subd. Rockford, IL

Add'l loc info: Lot: 13 Subdivision: Easton View

Location source: Aerial Photograph verified

Verified by: VJA on 4/9/2021

Permit Date: December 11, 1980 **Permit #:** 97765

COMPANY Raney, Sherman

FARM Garvin, Jim

DATE DRILLED January 24, 1981 **NO.**

ELEVATION 0' **COUNTY NO.** 21677

LOCATION

LATITUDE 42.288052 **LONGITUDE** -88.939868

COUNTY Boone **API#** 1200721677 00 **18-44N-3E**