

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
fill	0	3
topsoil	3	5
limestone	5	53
shale	53	217
dolomite	217	325

Total Depth

325

Casing: 6" BLACK ASTM A53B from 0' to 100'

Grout: PORTLAND CEMENT from 0 to 100

Water from rock at 285' to 325'

Static level 100' below casing top which is 1' above GL

Pumping level 104' when pumping at 10 gpm for 6 hr(s)

Permanent pump installed at 0' on 4/12/1999, with a capacity of 0 gpm

Owner Address: 596 S. Van Brocklin Freeport, IL

Address of well: Southview Dr. Lake Carroll, IL Lake Carroll IL

Add'l loc info: Lot: #36 Subdivision: Lake Carroll

Location source: Location from permit

Permit Date: November 30, 1998

Permit #:

COMPANY Bull, Jack D.

FARM Hasken, Rick / Bozin

DATE DRILLED April 9, 1999

NO.

ELEVATION 0'

COUNTY NO. 21468

LOCATION

LATITUDE 42.185089

LONGITUDE -89.888959

COUNTY Carroll

API# 1201521468 00

2-25N-5E