

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
topsoil	0	2
limestone	2	63
shale	63	80
limestone	80	87
soft shale	87	107
hard shale	107	205

Total Depth **205**

Casing: 6" .280 BLK ASTM A53B from 0' to 123'

Grout: PORTLAND CEMENT from 0 to 123

Water from rock at 135' to 205'

Static level 80' below casing top which is 1' above GL

Pumping level 82' when pumping at 10 gpm for 6 hr(s)

Permanent pump installed at 0' on 4/12/1999, with a capacity of 0 gpm

Owner Address: 596 S. Van Brocklin Freeport, IL

Address of well: Barrington Ct. Lake Carroll, IL Lake Carroll IL

Add'l loc info: Lot: #48 Subdivision: Lake Carroll
Section 23

Location source: Location from permit

Permit Date: November 30, 1998 **Permit #:** 015-124-98

COMPANY Bull, Jack D.

FARM Hasken, Rick - Guinta

DATE DRILLED April 6, 1999 **NO.**

ELEVATION 0' **COUNTY NO.** 21471

LOCATION

LATITUDE 42.181615 **LONGITUDE** -89.876666

COUNTY Carroll **API#** 1201521471 00 **12-25N-5E**