

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Dry Hole (water well)	Top	Bottom
top	0	3
yellow clay	3	12
embedded gray clay	12	24
sand & gravel	24	26
soft gravely gray clay	26	68
embedded gry clay couple sand streaks	68	92
embedded gravely brown clay	92	100
soft brown clay	100	111
sand	111	112
soft gray & green clay	112	121
embd gravely gry & grn clay sand streaks	121	134
medium sand to fine gravel	134	141
embedded gray clay	141	145
medium sand to medium gravel & rocks	145	157
fine to coarse sand	157	169
sand gravel & rocks	169	170
embedded gray clay sand streaks	170	180
embedded gray clay hard	180	197
embedded gray clay	197	259
fine to coarse sand	259	265
medium sand to fine gravel	265	281
medium sand to medium gravel & rocks	281	290
shale	290	292

Total Depth

292

Owner Address: Farmland Management ,

Address of well: 2625' W of Co. Rd. 900E, 2035' S of Co. Rd. 2400N

CHAM-13-01A

Permit Date:

Permit #:

COMPANY Grosch Irrigation

FARM Wood, Rob

DATE DRILLED May 9, 2013

NO. TH2

ELEVATION 772'

COUNTY NO. 27718

LOCATION

LATITUDE 40.218022

LONGITUDE -88.306117

COUNTY Champaign

API# 1201927718 00

4-20N-8E

ILLINOIS STATE GEOLOGICAL SURVEY

Page 2

Verified by: AJS on 9/6/2016

Permit Date:

Permit #:

COMPANY Grosch Irrigation

FARM Wood, Rob

DATE DRILLED May 9, 2013

NO. TH2

ELEVATION 772'

COUNTY NO. 27718

LOCATION

LATITUDE 40.218022

LONGITUDE -88.306117

COUNTY Champaign

API# 1201927718 00

4-20N-8E