

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Dry Hole (water well)	Top	Bottom
top	0	3
embedded brown & yellow clay	3	10
embedded gray clay	10	16
sand & gravel	16	20
soft sandy clay	20	30
embedded gray clay	30	40
soft embedded gry some sand & gravel	40	72
embedded brown clay	72	92
soft embedded brown clay	92	100
soft embedded brown & green clay	100	110
embedded gray clay	110	115
sand & gravel clay streaks	115	120
medium sand to fine gravel	120	126
medium sand to medium gravel & rocks	126	134
gray clay with sand streaks	134	138
medium sand to fine gravel	138	141
embedded gravely brown clay	141	170
embedded gravely gray clay hard	170	238
sand & gravel	238	242
medium sand to fine gravel clay streaks	242	250
medium sand to fine gravel	250	260
medium to coarse sand	260	274
embedded gray & green clay	274	280
shale	280	288
Total Depth		288

Owner Address: Farmland Management ,

Address of well:

Permit Date:

Permit #:

COMPANY Grosch Irrigation

FARM Wood, Rob

DATE DRILLED May 23, 2013

NO. TH-3

ELEVATION 763'

COUNTY NO. 27719

LOCATION

LATITUDE 40.215156

LONGITUDE -88.302324

COUNTY Champaign

API# 1201927719 00

4-20N-8E

ILLINOIS STATE GEOLOGICAL SURVEY

Page 2

1850' W of Co. Rd. 900E & 3050' S of Co. Rd. 2400N

CHAM-13-01B

Verified by: AJS on 9/6/2016

Permit Date:

Permit #:

COMPANY Grosch Irrigation

FARM Wood, Rob

DATE DRILLED May 23, 2013

NO. TH-3

ELEVATION 763'

COUNTY NO. 27719

LOCATION

LATITUDE 40.215156

LONGITUDE -88.302324

COUNTY Champaign

API# 1201927719 00

4-20N-8E