

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
sicl br mot trsa	0	15
sicl mot-gr trsa	15	20
sicl gr trsa	20	75
sa br fi-med cor	75	100

Total Depth **100**

Casing: 5" SDR 21 from -1' to 96'
 3" SCREEN from 96' to 100'

Screen: 4' of 3" diameter 0.012 slot

Grout: BENTONITE from 0 to 75
 WASHED GRAVEL from 95 to 100
 NATURAL SAND from 75 to 95

Water from sand at 75' to 100'

Static level 36' below casing top which is 1' above GL

Pumping level 40' when pumping at 10 gpm for 2 hr(s)

Permanent pump installed at 85' on 4/14/2016, with a capacity of 10 gpm

Remarks: Driller's Estimated Well Yield 50 gpm

Owner Address: 2940 CR 1800 E Rantoul, IL

Address of well: same as above

Location source: Global Positioning System verified

Permit Date: April 11, 2016

Permit #: 019-19-16

COMPANY Balding, Shane

FARM Suits, Virlon

DATE DRILLED April 12, 2016

NO.

ELEVATION '

COUNTY NO. 27799

LOCATION

LATITUDE 40.500256

LONGITUDE -88.150200

COUNTY Champaign

API# 1201927799 00

6-21N-10E