

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
brown clay	0	25
gray clay	25	105
gray shale soft	105	200

Total Depth 200

Grout: BENTONITE from to

Owner Address: 1226 Carlyle Rd Bartelso, IL

Address of well: same as above

Location source: Global Positioning System verified

[Imaged Log viewing help: New users please read this.](#)

[GET FILE](#)

Related File - Unknown File Type

Permit Date: March 13, 2023

Permit #: 027-C004-2023

COMPANY Hemmen, Jake

FARM Luitjohen, Brad

DATE DRILLED March 20, 2023

NO.

ELEVATION '

COUNTY NO. 27391

LOCATION

LATITUDE 38.536250

LONGITUDE -89.459990

COUNTY Clinton

API# 1202727391 00

17-1N-3W