

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
brown clay	0	22
sand	22	26
till	26	29
gray clay	29	34
brown sandstone	34	68
shale w/ streaks of lime	68	200

Total Depth **200**

Remarks: closed loop well system

Owner Address: 706 W. Diane Ct. Robinson, IL

Address of well: same as above

Location source: Global Positioning System verified

[Imaged Log viewing help: New users please read this.](#)

[GET FILE](#)

Related File - Unknown File Type

Permit Date: July 11, 2019

Permit #: 033-001-19

COMPANY Durbin, Kandra M.

FARM Lum, Mike

DATE DRILLED July 18, 2019

NO.

ELEVATION '

COUNTY NO. 38272

LOCATION

LATITUDE 39.015758

LONGITUDE -87.747989

COUNTY Crawford

API# 1203338272 00

28-7N-12W