

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
clay	0	70
gravel	70	73
clay	73	92
gravel	92	98

Total Depth **98**

Casing: 5" 200# PVC from -1' to 98'

Grout: BENTONITE from to

Water from gravel at ' to '

Static level 15' below casing top which is 1' above GL

Pumping level ' when pumping at 30 gpm for hr(s)

Address of well: 107 Main St. Maple Park, IL 60151 Maple Park IL

Location source: Location from the driller

Permit Date: August 3, 1992

Permit #: 5241

COMPANY Stone, Ronald D.

FARM First State Bank of Maple Park

DATE DRILLED August 3, 1992

NO.

ELEVATION '

COUNTY NO. 23804

LOCATION

LATITUDE 41.902129

LONGITUDE -88.602596

COUNTY DeKalb

API# 1203723804 00

36-40N-5E