

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
black dirt	0	2
yellow clay	2	18
blue clay	18	75

Total Depth **75**

Water from dry hole at 0' to 0'

Remarks: Dry hole - dry at 58' too

Owner Address: 825 N. Co. Rd. #1675 E Camargo, IL

Location source: Location from permit

Permit Date: November 21, 1996

Permit #:

COMPANY Luttrell, James

FARM Hatchel, Myron

DATE DRILLED December 16, 1996

NO.

ELEVATION 0'

COUNTY NO. 22732

LOCATION

LATITUDE 39.772180

LONGITUDE -88.154707

COUNTY Douglas

API# 1204122732 00

1-15N-9E