

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
top soil	0	5
yellow clay	5	31
blue clay	31	99
dirty fine sand	99	106
water sand	106	109

Total Depth **109**

Casing: 6" 280 WALL STEEL from 0' to 106'

Screen: 3' of 5" diameter 15 slot

Grout: BENSEAL from 0 to 0

Size hole below casing: 5"

Water from sand at 105' to 109'

Static level 3' below casing top which is 2' above GL

Pumping level 15' when pumping at 40 gpm for 1 hr(s)

Permanent pump installed at 0' on , with a capacity of 0 gpm

Owner Address: R.R.#1, P.O. Box #146 Carmen, IL

Location source: Location from permit

Permit Date: January 31, 1992

Permit #:

COMPANY Bjorklund, Llyod A.

FARM Boyd, Linda

DATE DRILLED February 6, 1992

NO.

ELEVATION 0'

COUNTY NO. 20797

LOCATION

LATITUDE 40.813553

LONGITUDE -90.960636

COUNTY Henderson

API# 1207120797 00

34-10N-5W