

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
sand	0	45
clay	45	95
sand	95	115

Total Depth **115**

Casing: 6" SDR 21 PVC from 0' to 100'
 6" SDR 21 PVC from 110' to 115'

Grout: BENTONITE from 0 to 65

Water from sand & gravel at 100' to 110'

Static level 30' below casing top which is 1' above GL

Pumping level 60' when pumping at 65 gpm for 1 hr(s)

Permanent pump installed at 0' on , with a capacity of 0 gpm

Owner Address: 11432 Lakeside Dr. Burlington, IA

Address of well: R.R. Box #99A Carman, IL Carman IL

Add'l loc info: Lot: 7,8,9 Subdivision: Sparrow

Location source: Location from permit

Permit Date: August 10, 1999

Permit #:

COMPANY Gingerich, Emery Duane

FARM Johnson, Bobby

DATE DRILLED August 11, 1999

NO.

ELEVATION 0'

COUNTY NO. 21069

LOCATION

LATITUDE 40.779592

LONGITUDE -91.026815

COUNTY Henderson

API# 1207121069 00

12-9N-6W