

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Dry Hole (water well), Plugged	Top	Bottom
topsoil	0	2
brown clay	2	15
gray clay	15	57
sandy shale	57	91
shale	91	97
sandy shale	97	100
sandstone dirty	100	112
shale	112	118
sandy shale	118	127
shale	127	131
sandy shale	131	150
dirty sandstone	150	156
sandy shale	156	167
limestone	167	170
underclay	170	171
limestone	171	174
sandy shale	174	186
shale	186	250
sandstone	250	258
shale	258	300

Total Depth **300**

Grout: BENSEAL from 0 to 60

Water from dry hole at ' to '

Static level 180' below casing top which is ' above GL

Pumping level ' when pumping at 0 gpm for 1 hr(s)

Remarks: dry hole, plugged

Owner Address: 8273 N 2250 St. Oblong, IL

Address of well: 9433 N 2225th St. Willow Hill, IL Willow Hill IL

Permit Date: June 20, 2006

Permit #: 079-02-06

COMPANY Tim Hacker

FARM Carter, David

DATE DRILLED October 15, 2006

NO. 1

ELEVATION '

COUNTY NO. 25418

LOCATION

LATITUDE 38.988627

LONGITUDE -87.956041

COUNTY Jasper

API# 1207925418 00

3-6N-14W

ILLINOIS STATE GEOLOGICAL SURVEY

Page 2

Location source: Location from permit

Permit Date: June 20, 2006

Permit #: 079-02-06

COMPANY Tim Hacker

FARM Carter, David

DATE DRILLED October 15, 2006

NO. 1

ELEVATION '

COUNTY NO. 25418

LOCATION

LATITUDE 38.988627

LONGITUDE -87.956041

COUNTY Jasper

API# 1207925418 00

3-6N-14W