

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well, Plugged	Top	Bottom
topsoil	0	1
fill (sandy clay & gravel)	1	12
gravelly sand silt	12	22
sand gravel silt	22	28
gray coarse sand gravel	28	44

Total Depth **44**

Casing: 12" STEEL from 2' to 30'

12" SCREEN from 30' to 42'

Screen: 12' of 12" diameter slot

Grout: PEA GRAVEL from 12 to 44

Water from gravel at 12' to 44'

Static level 19' below casing top which is 2' above GL

Remarks: temp dewat, sealed 12/9/2009

Owner Address: 3826 Karl Madsen Drive St. Charles, IL

Address of well: same as above

Add'l loc info: Subdivision: 911 Center

Location source: Location from permit

Permit Date: September 23, 2009 **Permit #:** SC089-0108-09

COMPANY Kerry, Charles M.

FARM Tri-Com Dispatch Center

DATE DRILLED September 30, 2009 **NO.** 2

ELEVATION ' **COUNTY NO.** 36686

LOCATION

LATITUDE 41.903506 **LONGITUDE** -88.367918

COUNTY Kane **API#** 1208936686 00 **31-40N-8E**