

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
clay	0	72
gravel	72	85
gray clay	85	100
gray clay sticky	100	123
gravel	123	132
clay	132	136
broken rock	136	139
lime	139	167
broken lime crevices, lots of water	167	172
lime gray	172	210

Total Depth **210**

Casing: 12" STEEL from -2' to 141'

Grout: CEMENT from 0 to 141

Static level 37' below casing top which is ' above GL

Pumping level 50' when pumping at 1034 gpm for 8 hr(s)

Permanent pump installed at ' on , with a capacity of gpm

Sample set # 70498 5' - 210' Received: 6/12/2015

Address of well: Junction of Rt.1/CR 37

Location source: Aerial Photograph verified

Verified by: VJA on 10/30/2015

Permit Date: **Permit #:**

COMPANY Layne & Western Co.

FARM St. Anne Well

DATE DRILLED November 28, 2011 **NO.** 5

ELEVATION ' **COUNTY NO.** 27718

LOCATION 120'N line, 210'W line of NW

LATITUDE 41.020573 **LONGITUDE** -87.731690

COUNTY Kankakee **API#** 1209127718 00 **9-29N-12W**