

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
yellow clay	0	16
blue clay	16	102
sand & clay	102	137
fine sand	137	148
coarse sand	148	152

Total Depth **152**

Casing: 2" GALV PIPE from 0' to 148'

1" MIDWEST SCREEN from 148' to 152'

Screen: 4' of 1" diameter 60 slot

Water from coarse sand at 148' to 152'

Static level 70' below casing top which is 0' above GL

Pumping level 0' when pumping at 10 gpm for 1 hr(s)

Driller's Log filed.

Address of well: Crooked Lake

Location source: Location from the driller

Permit Date:

Permit #:

COMPANY Madsen, Charles

FARM Woodin, Mrs.

DATE DRILLED January 1, 1957

NO. 1

ELEVATION 0'

COUNTY NO. 02198

LOCATION

LATITUDE 42.421751

LONGITUDE -88.051641

COUNTY Lake

API# 1209702198 00

34-46N-10E