

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
top soil	0	5
clay	5	9
sand & gravel	9	35
clay	35	46
sand	46	62
clay	62	93
sand & gravel	93	101
clay	101	110

Total Depth **110**

Casing: 5" SDR 21 200# PVC from 0' to 98'

4" SCREEN PKG from 95' to 101'

Screen: 3' of 4" diameter 20 slot

Grout: SLURRY from 0 to 98

Size hole below casing: 4"

Water from drift at 98' to 101'

Static level 15' below casing top which is 40' above GL

Pumping level ' when pumping at gpm for 24 hr(s)

Owner Address: 30099 N. Fairfield Rd. Grayslake, IL

Address of well: 4410 Bayview Dr. Crystal Lake, IL. Crystal Lake IL

Add'l loc info: Lot: 1-4 Subdivision: Bayview Beach
Block 7

Location source: Aerial Photograph verified

Verified by: VJA on 7/6/2012

Permit Date: January 4, 1994

Permit #: 111-F7964-94

COMPANY Hutchings, Clyde A.

FARM Elkins Construction

DATE DRILLED August 5, 1994

NO.

ELEVATION '

COUNTY NO. 33332

LOCATION

LATITUDE 42.265733

LONGITUDE -88.224614

COUNTY McHenry

API# 1211133332 00

30-44N-9E