

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
black dirt	0	3
pea gravel	3	36
gravel 3/8"	36	60
sand	60	83
gravel (small)	83	93

Total Depth

93

Casing: 5" PVC SDR21 from -1' to 72'

5" BLACK STEEL A53B from 72' to 93'

5" STAINLESS STL SCREEN from ' to '

Screen: 3' of 5" diameter slot

Grout: WYOBEN DF from 0 to 93

Water from gravel at 83' to 93'

Static level 40' below casing top which is 1' above GL

Pumping level 85' when pumping at 10 gpm for 4 hr(s)

Permanent pump installed at 85' on 11/29/2007, with a capacity of 10 gpm

Remarks: Driller's Estimated Well Yield 20 gpm

Owner Address: 5019 Burman Dr Crystal Lake, IL

Address of well: same as above

Add'l loc info: Lot: 18 Subdivision: Crystal Lake Ests

Location source: Global Positioning System verified

Verified by: VJA on 3/27/2012

Permit Date: August 1, 2007

Permit #: 111-0387-07

COMPANY Snelten, Stephen A.

FARM Ormsby, Richard

DATE DRILLED November 29, 2007

NO.

ELEVATION '

COUNTY NO. 43392

LOCATION

LATITUDE 42.238694

LONGITUDE -88.295778

COUNTY McHenry

API# 1211143392 00

3-43N-8E