

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
top soil	0	2
brown clay	2	6
fine sand	6	13
embedded brown clay	13	30
sand	30	43
embedded gray clay white/sand layers	43	73
fine sand	73	80
fine/medium sand	80	100
fine sand	100	156
fine/medium sand	156	160
medium/coarse sand	160	173

Total Depth **173**

Casing: 5" PLAIN PVC from 0' to 169'

5" SS SCREEN from 169' to 173'

Screen: 4' of 5" diameter 0.012 slot

Grout: BENTONITE from 4 to 25

Static level 75' below casing top which is 0' above GL

Owner Address: R.R. #1 Easton, IL

Location source: Location from permit

Permit Date: July 21, 1992

Permit #: 022178

COMPANY Greenfield, Ed

FARM Kirby, Ed

DATE DRILLED September 14, 1992

NO.

ELEVATION 0'

COUNTY NO. 21268

LOCATION

LATITUDE 40.164466

LONGITUDE -89.886844

COUNTY Mason

API# 1212521268 00

21-20N-7W