

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
clay	0	35
fractured rock	35	40
shale	40	50
voids	50	60
limestone	60	110
shale	110	130
limestone	130	150

Total Depth **150**

Remarks: closed loop well system

Owner Address: 5356 LCR Rd. Waterloo, IL

Address of well: same as above

Location source: Global Positioning System verified

[Imaged Log viewing help: New users please read this.](#)

[GET FILE](#)

Related File - Unknown File Type

Permit Date: May 22, 2019

Permit #: 133-026-19

COMPANY Durbin, Kandra M.

FARM Stutzman, Dianne

DATE DRILLED May 31, 2019

NO.

ELEVATION '

COUNTY NO. 23635

LOCATION

LATITUDE 38.132500

LONGITUDE -90.102222

COUNTY Monroe

API# 1213323635 00

15-3S-10W