

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
clay	0	35
drift mix sand	35	153
lime shelly broken	153	163
shale darts	163	220
some cale white shale	220	225
shale limestone broken	225	230
shale	230	250
lime very hard	250	260
lime broken	260	265

Total Depth **265**

Casing: 6" 19 L B from 0' to 153'
 5" PLASTIC from 148' to 265'

Water from broken limestone at 225' to 230'

Static level 100' below casing top which is 0' above GL

Driller's Log filed.

Owner Address: 1820 S. Douglas Sprigfield, IL

Location source: Location from permit

Permit Date: September 1, 1978 **Permit #:** 78834

COMPANY Chadwick, G. W.

FARM Spring Valle Contr.

DATE DRILLED September 9, 1978 **NO.**

ELEVATION 0' **COUNTY NO.** 20756

LOCATION

LATITUDE 39.799312 **LONGITUDE** -90.222937

COUNTY Morgan **API#** 1213720756 00 **33-16N-10W**