

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
black dirt	0	1
brown yellow clay	1	16
sand & gravel	16	18
gray clay	18	46
gray sand	46	47
gray clay	47	49
sand & gravel	49	51
gray clay	51	53

Total Depth

53

Casing: 6" SDR 21 from -1' to 14'
 36" CEMENT from 14' to 53'

Grout: BENTONITE from 11 to 12
 WASHED PEA GRAVEL from 12 to 53

Water from sand & gravel at 46' to 51'

Remarks: Driller's Estimated Well Yield 20 gpm

Owner Address: 19026 N. Hakes Rd. Edelstein, IL

Address of well: same as above

Location source: Location from permit

Permit Date: May 23, 2007

Permit #: 143-W0023-07

COMPANY Michael Dryden

FARM Ellis, David

DATE DRILLED May 30, 2007

NO.

ELEVATION '

COUNTY NO. 35106

LOCATION

LATITUDE 40.920162

LONGITUDE -89.638131

COUNTY Peoria

API# 1214335106 00

19-11N-8E