

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
yellow clay	0	40
lime & shale	40	247
sandstone	247	319
limestone	319	320

Total Depth 320

Casing: 6" STEEL from 0' to 252'

Size hole below casing: 6"

Static level 104' below casing top which is 1' above GL

Pumping level 0' when pumping at 30 gpm for 1 hr(s)

Driller's Log filed.

Owner Address: R.R. #1 Ruma, IL

Location source: Platbook verified

Verified by: DAG on 8/17/2007

Permit Date: March 25, 1977

Permit #: 58257

COMPANY Haudrich Drlg.

FARM St Patrick Church

DATE DRILLED April 27, 1977

NO.

ELEVATION '

COUNTY NO. 23100

LOCATION

LATITUDE 38.132306

LONGITUDE -90.008822

COUNTY Randolph

API# 1215723100 00

5-5S-8W