

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
top soil	0	3
clay	3	12
lime	12	89
broken lime & shale	89	94
lime w/trace of sh	94	200

Total Depth **200**

Casing: 5" STANDARD T&C from -2' to 99'

Grout: CEMENT from 0 to 99

Size hole below casing: 4.86999988555908"

Water from rock at 180' to 200'

Static level 29' below casing top which is 2' above GL

Pumping level 40' when pumping at 18 gpm for 4 hr(s)

Permanent pump installed at 0' on , with a capacity of 0 gpm

Owner Address: 3300 5th Avenue Moline, IL

Location source: Location from permit

Permit Date: April 12, 1978 **Permit #:** 72984

COMPANY Winslow, Loring Field

FARM Moline Park & Rec Board

DATE DRILLED May 3, 1978 **NO.** 1

ELEVATION 0' **COUNTY NO.** 21842

LOCATION 905'N line, 30'W line of SW NW SW

LATITUDE 41.459758 **LONGITUDE** -90.451484

COUNTY Rock Island **API#** 1216121842 00 **13-17N-1W**