

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
dark brown silty clay	0	15
gray clayey silt	15	23
dark olive gray silt	23	25
brown silt	25	28

Total Depth **28**

Casing: 2" SCH 40 PVC from -3' to 17'

2" SCH 40 from 27' to 28'

2" SCREEN from 17' to 27'

Screen: 10' of 2" diameter 0.01 slot

Grout: BENTONITE CHIPS from 3 to 15

SILICA SAND from 15 to 28

Water from silt at 23' to 28'

Address of well: 17201 20th Ave. N. East Moline, IL 61244 East
Moline IL

Location source: Global Positioning System verified

[Imaged Log viewing help: New users please read this.](#)

[GET FILE](#)

Related File - Unknown File Type

Permit Date:

Permit #:

COMPANY Testing Service Corporation

FARM Upper Rock Island Co. Landfill, Inc

DATE DRILLED April 14, 2014

NO.

ELEVATION 681' GL

COUNTY NO. 24407

LOCATION

LATITUDE 41.547278

LONGITUDE -90.381472

COUNTY Rock Island

API# 1216124407 00

16-18N-1E