

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
well repair		

Total Depth

Casing: 5" A53 from ' to '

Remarks: well repair

Owner Address: 23107 Rt 2 92 Port Byron, IL

Address of well: same as above

Location source: Location from the driller

Permit Date: July 1, 2019

Permit #: 161-WW10-2019

COMPANY Latta, Mark Duane

FARM Conner, James

DATE DRILLED July 29, 2019

NO.

ELEVATION '

COUNTY NO. 24713

LOCATION

LATITUDE 41.559038

LONGITUDE -90.291290

COUNTY Rock Island

API# 1216124713 00

8-18N-2E