

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
black silty clay	0	2
brown silty clay	2	5
brown & gray silty clay	5	10
brown silty clay some sand med	10	16
gray silty clay some sand med	16	38
gray sandstone	38	42
gray shale	42	52

Total Depth **52**

Casing: 6" PVC SDR 21 from -1' to 14'
 30" FIBERGLASS from 14' to 52'

Grout: BENT CHIPS from 13 to 14

Water from sandstone at 380' to 420'

Remarks: Driller's Estimated Well Yield 10 gpm

Owner Address: 18869 Boston Rd Virden, IL

Address of well: same as above

Location source: Global Positioning System verified

Permit Date: September 22, 2020 **Permit #:** 167-025-2020

COMPANY Reynolds Well Drilling

FARM Hays, Luke

DATE DRILLED October 13, 2020 **NO.**

ELEVATION ' **COUNTY NO.** 26882

LOCATION

LATITUDE 39.525306 **LONGITUDE** -89.709917

COUNTY Sangamon **API#** 1216726882 00 **35-13N-5W**