

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
black top soil	0	2
brown sandy clay	2	14
brown sand	14	16
gray clay	16	50

Total Depth **50**

Casing: 36" CONCRETE from 14' to 50'
6" PVC SDR 21 from -1' to 14'

Grout: BENTONITE from to

Water from sand at 14' to 16'

Static level 7' below casing top which is 1' above GL

Pumping level ' when pumping at 1 gpm for hr(s)

Remarks: Driller's Estimated Well Yield 1 gpm

Owner Address: 9598 N 1130 East Rd Catlin, IL

Address of well: 9743 N 1130 East Rd Catlin, IL Catlin IL

Location source: Global Positioning System verified

Permit Date: December 8, 2022 **Permit #:** 183-2681-2022

COMPANY Harper, David

FARM Bedinger, Charles

DATE DRILLED December 10, 2022 **NO.**

ELEVATION ' **COUNTY NO.** 27233

LOCATION

LATITUDE 40.008542 **LONGITUDE** -87.727593

COUNTY Vermilion **API#** 1218327233 00 **21-18N-12W**