

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
sandy clay	0	14
yellow limestone	14	40
white limestone	40	75
gray limestone	75	122
shale	122	290
limestone	290	630
Glenwood	630	670
white sandstone	670	785

Total Depth

785

Casing: 6" SA53B from -1' to 686'

Grout: BENTONITE from 0 to 50

BENTONITE from 50 to 686

Water from sandstone at 670' to 785'

Static level 215' below casing top which is 0' above GL

Pumping level 240' when pumping at 23 gpm for 4 hr(s)

Permanent pump installed at 0' on 3/28/2000, with a capacity of 0 gpm

Owner Address: 603 West 1st St. Lyndon, IL

Address of well: 23463 Carroll Rd. Morrison, IL Morrison IL

Location source: Location from permit

[Imaged Log viewing help: New users please read this.](#)

[GET FILE](#)

Scanned Documents

Permit Date: August 26, 1999

Permit #:

COMPANY Martin, Jonas Willard

FARM Cady, Richard W.

DATE DRILLED March 28, 2000

NO. 1

ELEVATION 0'

COUNTY NO. 22615

LOCATION

LATITUDE 41.922985

LONGITUDE -89.989343

COUNTY Whiteside

API# 1219522615 00

1-22N-4E