

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
WELL REPAIR PERMIT 197-102-18		
clay & gravel	0	85
limestone	85	160

Total Depth **160**

Casing: 5" BLACK from 0' to 85'

Water from limestone at 85' to 160'

Remarks: well repair raise casing

Driller's Log filed.

Owner Address: 7416 W. 160th Pl Tinley Park, IL

Address of well: 18311 Virginia Ln.

Add'l loc info: Lot: 20 Subdivision: Sugarbrook

Location source: Aerial Photograph verified

Verified by: VJA on 4/19/2019

Permit Date: May 29, 1975

Permit #: 38099

COMPANY Rob, Ronald Gene

FARM James, J.

DATE DRILLED October 15, 2018

NO. 1062

ELEVATION '

COUNTY NO. 25188

LOCATION

LATITUDE 41.555878

LONGITUDE -87.933877

COUNTY Will

API# 1219725188 00

2-35N-11E