

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
topsoil	0	2
clay	2	92
broken rock	92	97
limestone	97	140

Total Depth **140**

Casing: 6" SDR 17 PVC from 0' to 100'

Grout: BENTONITE from 0 to 100

Size hole below casing: 5.5"

Water from limestone at 100' to 140'

Static level 95' below casing top which is 1' above GL

Remarks: did not install pump

Owner Address: 1358 N. Cedar Rd. New Lenox, IL

Address of well: 609 Blackhawk St. Joliet, IL Joliet IL

Add'l loc info: Lot: 18 & 19 Subdivision: Belmont

Location source: Aerial Photograph verified

Verified by: VJA on 10/2/2014

Imaged Log viewing help: New users please read this.

GET FILE

Related File - Unknown File Type

Permit Date: August 7, 1998

Permit #: 197-98-0094-J

COMPANY Leasure, Arthur C.

FARM Macropoulos, Joy

DATE DRILLED September 4, 1998

NO. 1

ELEVATION 0'

COUNTY NO. 38124

LOCATION

LATITUDE 41.537321

LONGITUDE -88.038079

COUNTY Will

API# 1219738124 00

12-35N-10E