

ILLINOIS STATE GEOLOGICAL SURVEY

Page 1

Water Well	Top	Bottom
topsoil	0	2
clay	2	32
broken limestone	32	47
limestone	47	85

Total Depth **85**

Casing: 6" SDR 21 PVC from 0' to 50'

Grout: BENTONITE from 0 to 50

Water from limestone at 50' to 85'

Owner Address: % Freedom Builders 8611 West 120th St. Palos Park,
IL

Address of well: 21111 Alicia Ct. Lockport, IL Lockport IL

Add'l loc info: Lot: 25 Subdivision: Prairie View Estates

Location source: Aerial Photograph verified

Verified by: VJA on 6/25/2014

Imaged Log viewing help: New users please read this.

GET FILE

Related File - Unknown File Type

Permit Date: August 11, 1998

Permit #: 197-98-0063N

COMPANY Leasure, Arthur C.

FARM Schubert, Micheal

DATE DRILLED August 25, 1998

NO. 1

ELEVATION 0'

COUNTY NO. 39380

LOCATION

LATITUDE 41.593483

LONGITUDE -88.130534

COUNTY Will

API# 1219739380 00

19-36N-10E